

# Inspection Photos

March 27th, 2026

Operator: Logos Operating

Location ID: 325181

Inspection Document #: 714003534

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bondad 33-10 6



**Photo 1.** 2024 NAIP imagery of the project area (highlighted in green) and associated access road (highlighted in red).

March 27, 2026  
157° SE



**Photo 2.** View of the project area taken from the northern edge facing center.

March 27, 2026  
358° N



**Photo 3.** Cardinal photo taken from the center of the project area facing north.

March 27, 2026  
187° S



**Photo 4.** Cardinal photo taken from the center of the project area facing south.



March 27, 2026  
171° S



**Photo 5.** Adjacent reference area.



Inspection Photos  
Location Name: Bondad 33-10 6

March 27, 2026  
77° E



**Photo 6.** View of the access road. Portions of the access road has establishment of desirable vegetation. Other portions remain bare with active erosion issues.



March 27, 2026  
123° SE



**Photo 7.** View of project area vegetation transect starting point facing southwest.

Inspection Photos  
Location Name: Bondad 33-10 6



**Photo 8.** Aerial view of project area vegetation transect midpoint; transect midpoint facing NE and SW.

Inspection Photos  
Location Name: Bondad 33-10 6



**Photo 9.** View of project area vegetation transect end point facing northwest.



Inspection Photos  
Location Name: Bondad 33-10 6



**Photo 10.** View of reference area vegetation transect starting point facing Southeast.

Inspection Photos  
Location Name: Bondad 33-10 6



**Photo 11.** Aerial view of reference area vegetation transect midpoint; transect midpoint facing NE and SW.

Inspection Photos  
Location Name: Bondad 33-10 6



March 27, 2026  
298° NW

**Photo 12.** View of reference area vegetation transect endpoint facing NW.

