

Inspection Photos

March 27th, 2026

Operator: Hilcorp Energy

Location ID: 325012

Inspection Document #: 714003536

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sever 1

March 27, 2026
0° N



Photo 1. View of the well pad taken from the access point facing center.

March 27, 2026
298° NW



Photo 2. Interim reclamation vegetation.

Inspection Photos
Location Name: Sever 1

March 27, 2026
148° SE



Photo 3. View of deep rutting occurring on the access road.