

# Inspection Photos

March 27th, 2026

Operator: Hilcorp Energy

Location ID: 326093

Inspection Document #: 714003537

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Carter Ute 107

March 27, 2026  
21° N



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos  
Location Name: Carter Ute 107



**Photo 2.** Black tarp trash observed littered through the interim reclamation areas.

Inspection Photos  
Location Name: Carter Ute 107



**Photo 3.** Stormwater BMPs installed on edge of active pad.  
No active erosion issues were observed during this inspection.

March 27, 2026  
332° NW



**Photo 4.** Interim reclamation vegetation.

