

Inspection Photos

March 27th, 2026

Operator: BP America

Location ID: 325595

Inspection Document #: 714003539

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bonds 3E



Photo 1. 2024 NAIP imagery of the project area (highlighted in Green).

March 27, 2026
34° NE



Photo 2. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Bonds 3E



Photo 3. View of electrical wiring that remains on location.



Inspection Photos
Location Name: Bonds 3E



Photo 4. View of large patches of Redstem filaree observed around the location. Colorado List C noxious weed.

March 27, 2026
347° N



Photo 5. Cardinal photo taken from the center of the project area facing north.

March 27, 2026
185° S



Photo 6. Cardinal photo taken from the center of the project area facing south.

March 27, 2026
302° NW



Photo 7. View of location cut slope facing northwest. Demonstrating that location has not been recontoured.



March 27, 2026
166° S



Photo 8. View of location fill slope facing south. Demonstrating that location has not been recontoured.