

# INSPECTION PHOTOS

**Well: VPR C 13**

**API #: 05-071-06863**

**INSPECTION DOC #: 716302114**

**Operator: WAPITI OPERATING LLC 10351**

**Inspection date: 4/1/2026**

**County: Las Animas**



Network: Apr 1, 2026 at 1:27:52 PM MDT  
Local: Apr 1, 2026 at 1:27:52 PM MDT  
+37.010841, -104.790874

PHOTO 2: WELL SIGN



Network: Apr 1, 2026 at 1:27:20 PM MDT  
Local: Apr 1, 2026 at 1:27:20 PM MDT  
+37.010788, -104.791029

PHOTO 3: LOCATION.



Network: Apr 1, 2026 at 1:27:28 PM MDT  
Local: Apr 1, 2026 at 1:27:28 PM MDT  
+37.010788, -104.791029

PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: WEEDS NOT MAINTAINED INSIDE ELECTRIC PANEL FENCE. **MAINTAIN WEEDS PER RULE 606. CA DATE 4/15/2026.**