

# INSPECTION PHOTOS

Well: JAROSA 32-33 WD

API #: 05-071-08532

INSPECTION DOC #: 716302041

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/2/2026

County: Las Animas



Network: Apr 2, 2026 at 10:09:37 AM MDT  
Local: Apr 2, 2026 at 10:09:37 AM MDT  
+37.304754, -104.782972

PHOTO 2: WELL SIGN



Network: Apr 2, 2026 at 10:07:30 AM MDT  
Local: Apr 2, 2026 at 10:07:30 AM MDT  
+37.304633, -104.784687

PHOTO 3: LOCATION.



PHOTO 4: TR WELLHEAD AND EQUIPMENT.



Network: Apr 2, 2026 at 10:08:16 AM MDT  
Local: Apr 2, 2026 at 10:08:16 AM MDT  
+37 304689 -104 783935

PHOTO 5: SIGN WITH ALL WELLS SERVICED BY TANK BATTERY NOT POSTED. **POST SIGN PER RULE 605e. CA DATE 5/2/2026.**



PHOTO 6: 210 BBL TANK BATTERY.




PHOTO 7: LINED PRODUCED WATER PIT.



Network: Apr 2, 2026 at 10:07:52 AM MDT  
Local: Apr 2, 2026 at 10:07:52 AM MDT  
+37.304630,-104.784253  
© 2025 DNR

PHOTO 8: FILTER HOUSE.