

INSPECTION PHOTOS

Well: RAMPART 43-33

API #: 05-071-07798

INSPECTION DOC #: 716302128

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/2/2026

County: Las Animas



Network: Apr 2, 2026 at 1:18:51 PM MDT
Local: Apr 2, 2026 at 1:18:51 PM MDT
+37.301003, -104.780191
1153 DT

PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



Network: Apr 2, 2026 at 1:20:18 PM MDT
Local: Apr 2, 2026 at 1:20:18 PM MDT
+37.300991, -104.730217
15000

PHOTO 4: TR WELLHEAD AND EQUIPMENT. Vacuum pump observed on well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. CA DATE 4/17/2026.