

INSPECTION PHOTOS

Well: BELARDE 12-34

API #: 05-071-09005

INSPECTION DOC #: 716302130

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/2/2026

County: Las Animas

WDID 1810074 / Permit # 72308

EVERGREEN

NATURAL RESOURCES LLC

BELARDE 12-34

API 05-071-09005

SW NW SECTION 34-31S-66W

CR 43.5 COC57890A

LAT. 37.30513/LONG. -104.77552

EMERGENCY No. 911 or 719-846-7898 (24 Hrs)

Network: Apr 2, 2026 at 1:56:00 PM MDT

Local: Apr 2, 2026 at 1:56:00 PM MDT

+37.305308, -104.775309

PHOTO 2: WELL SIGN



Network: Apr 2, 2026 at 1:53:52 PM MDT
Local: Apr 2, 2026 at 1:53:52 PM MDT
+37.305296, -104.774882

PHOTO 3: LOCATION.



Network Apr 2, 2026 at 1:54:20 PM MDT
Local Apr 2, 2026 at 1:54:20 PM MDT
+37.305112, -104.775374
057814

PHOTO 4: TR WELLHEAD AND EQUIPMENT.



Network: Apr 2, 2026 at 1:54:50 PM MDT
Local: Apr 2, 2026 at 1:54:50 PM MDT
+37 305163 -104 775494

PHOTO 5: AREA OF IMPACTED SOIL AROUND WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. THIS IS THE 3RD NOTICE FOR THIS CA. IT APPEARS THAT THE OTHER AREAS OF IMPACTED SOILS AROUND LOCATION HAVE BEEN ADDRESSED HOWEVER AROUND THE WELLHEAD IS GETTING WORSE THE LEAK MUST BE ADDRESSED IMMEDIATE ACTION IS REQUIRED.