

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNE

Location #: 302509



Photo #1

Bashor State AA 16-02 (123-29254) Wellsite

Temporarily Abandoned | TA

CA: Undesirable weeds

Affix sign to well or fencing.



Photo #2

Bashor State AA 16-02 Wellsite

Temporarily Abandoned | TA

macro view

CA: Undesirable weeds



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNE

Location #: 302509



Photo #3

Bashor State AA 16-02 Wellsite
Temporarily Abandoned | TA
Wellsite(s) entrance



Photo #4

**Bashor State AA 16-08, 16-01, 16-02, 16-07,
Bashor State 16-18** Battery site
Abandoned: ALL Equipment Removed
Formerly served:
Bashor State AA 16-09, 16-17, Bashor State 16-22;
Plugged & Abandoned | PA; 3-well(s)



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources