

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENE

Location #: 302510




Photo #1

Bashor State AA 16-01 (123-29255) Wellsite
Temporarily Abandoned | TA



Photo #2

Bashor State AA 16-01 Wellsite
Temporarily Abandoned | TA
macro view



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENE

Location #: 302510



Photo #3

Bashor State AA 16-01 Wellsite
Temporarily Abandoned | TA
Wellsite(s) entrance



Photo #4

Bashor State AA 16-08, 16-01, 16-02, 16-07,
Bashor State 16-18 Battery site
Abandoned: ALL Equipment Removed
Formerly served:
Bashor State AA 16-09, 16-17, Bashor State 16-22;
Plugged & Abandoned | PA; 3-well(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources