

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3940 Entrance to location



Photo # 3980 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3941 Location



Photo # 3963 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3979 Location



Photo # 3994 SW corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3996 NW corner of location



Photo # 3997 NE corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3998 SE corner of location



Photo # 3943 Oily waste and stained soil

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026




Photo # 3949 Oily waste and stained soil



Photo # 3951 Oily waste and stained soil

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3953 Stained soil



Photo # 3954 Stained soil

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3988 Stained soil

Photo # 3990 Stained soil

Inspection/Audit Photos

Location: KT RESOURCES LLC FEDERAL #B-25-2-97 Pad

Location ID: 315965

Date: 03/26/2026



Photo # 3991 Stained soil