

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENW

Location #: 310240



Photo #1

Bashor State AA 16-6 (123-26118) Wellsite

Temporarily Abandoned | TA

*Comment: Emergency number peeling.
Consider replacing.
Post TA tag at well.*



Photo #2

Bashor State AA 16-6 Wellsite

Temporarily Abandoned | TA

macro view



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENW

Location #: 310240



Photo #3

Bashor State AA 16-06 Wellsite
Temporarily Abandoned | TA
Wellsite(s) entrance



Photo #4

Bashor State AA 16-6 Battery site
Abandoned: ALL Equipment Removed
Formerly served:
Bashor State AA 16-3, 16-04, 16-5, 16-12, 16-19, 16-20
Plugged & Abandoned | PA; 6-well(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources