

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENW

Location #: 302516



Photo #1

Bashor State AA 16-19 (123-29261) Wellsite

Plugged & Abandoned | PA

Cut / Capped

≈ 35 yds.



Photo #2

Bashor State AA 16-6 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Bashor State AA 16-3, 16-04, 16-5, 16-12, 16-19, 16-20

Plugged & Abandoned | PA; 6-well(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources