

Inspection Photos

Location Name: PEPPLER-66N63W /17SESW

Location #: 306256



Photo #1

Peppler 17-34 (123-24307) Wellsite

Temporarily Abandoned | TA

Comment: Emergency number peeling.

Consider replacing.

Post TA tag at well.



Photo #2

Peppler 17-34 Wellsite

Temporarily Abandoned | TA

macro view



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PEPPLER-66N63W /17SESW

Location #: 306256



Photo #3

Peppler 17-34 Wellsite
Temporarily Abandoned | TA
Wellsite(s) entrance



Photo #4

Peppler 17-34 Battery site
Abandoned: ALL Equipment Removed
Formerly served:
Peppler 17-31, 17-33, Peppler PC AA 17-25;
Plugged & Abandoned | PA; 3-well(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources