

Inspection Photos

03/24/2026

Operator: GRMR Oil and Gas LLC #10524

Location ID: 313249

Inspection Doc: 719201007

Moffat County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 1: Photos showing an overview of the location looking north and south, respectively. Vegetation appears to meet 1004 reclamation requirements of desirable, perennial and uniform vegetation of at least eighty (80) percent cover.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 2: Photos showing an overview of the location looking east and west, respectively. Vegetation appears to meet 1004 reclamation requirements of desirable, perennial and uniform vegetation of at least eighty (80) percent cover.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 3: Photos showing an overview of the southern and northern portions of the location, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 4: Photo showing a general overview of the location from the access road. Yellow arrow shows the nearby reference area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 5: Photos showing Google Earth imagery of the location from 2006 and 2011, respectively. The access road appears to pre-exist Oil & Gas activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 6: Photos showing an overview of the access road next to the location. The road pre-dates the location; however, gravel has been removed and this portion of the road reseeded.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 313249



Photo 7: Photo showing an example of the nearby reference area, directly east of the location. The reference area is characterized as a big sagebrush shrubland.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources