

Final Reclamation Inspection

March 20, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328225

Inspection Document #: 718801505

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-TEACHER #10-14A
Location ID: 328225



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*) were observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HSR-TEACHER #10-14A
Location ID: 328225



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: HSR-TEACHER #10-14A
Location ID: 328225



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the location, facing northwest. Photo illustrates that reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed.

Inspection Photos
Location Name: HSR-TEACHER #10-14A
Location ID: 328225



Photo 7. Photo taken of the access road to the location, facing east, away from the location. See comments under Photo 6.



Photo 8. Photo taken of the reference area to the location, south of the location, facing southeast. Photo illustrates perennial grass and weedy annual vegetation.

