

# Final Reclamation Inspection

March 20, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 306450

Inspection Document #: 718801511

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MURRAY #21-14  
Location ID: 306450



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: MURRAY #21-14  
Location ID: 306450



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: MURRAY #21-14  
Location ID: 306450



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



**Photo 6.** Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities appear to have taken place and vegetation is establishing.

Inspection Photos  
Location Name: MURRAY #21-14  
Location ID: 306450



**Photo 7.** Photo taken of the tank battery location, facing east. See comments under Photo 6.



**Photo 8.** Photo taken of the tank battery location, facing southwest. See comments under Photo 6.



Inspection Photos  
Location Name: MURRAY #21-14  
Location ID: 306450



**Photo 9.** Photo taken of the tank battery location, facing southwest.



**Photo 10.** Photo taken of the reference area to the location, north of the location, facing northwest. Photo illustrates perennial grass vegetation.