

# Final Reclamation Inspection

March 20, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 317581

Inspection Document #: 718801527

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: UPRR 21 PAN AM C #1  
Location ID: 317581



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not yet meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos

Location Name: UPRR 21 PAN AM C #1

Location ID: 317581



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: UPRR 21 PAN AM C #1  
Location ID: 317581



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



**Photo 6.** Photo taken of the access road to the well location, facing north. Photo illustrates that final reclamation activities do not appear to have taken place along the access road. Gravel and bare ground remain.

## Inspection Photos

Location Name: UPRR 21 PAN AM C #1

Location ID: 317581



**Photo 7.** Photo taken of the tank battery location, facing southwest. Photo illustrates that final reclamation activities have not taken place along the access road and vegetation has not yet established to Rule 1004 standards.



**Photo 8.** Photo taken of the tank battery location, facing north. See comments under Photo 7.



Inspection Photos

Location Name: UPRR 21 PAN AM C #1

Location ID: 317581



**Photo 9.** Photo taken of the tank battery location, facing east. See comments under Photo 7.



**Photo 10.** Photo taken of the tank battery location, facing west. See comments under Photo 7.



Inspection Photos  
Location Name: UPRR 21 PAN AM C #1  
Location ID: 317581



**Photo 11.** Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass vegetation.