

Final Reclamation Inspection

March 20, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 332479

Inspection Document #: 718801523

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PENTON #23-11
Location ID: 332479



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not yet meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: PENTON #23-11
Location ID: 332479



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1. Photo illustrates that final reclamation activities have taken place along the access road.



Inspection Photos
Location Name: PENTON #23-11
Location ID: 332479



Photo 5. Photo taken of ground cover at the well location. Photo illustrates mulch and bare ground.



Photo 6. Photo taken of the reference area to the location, northwest of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

