

Inspection Photos  
Location Name: BASHOR PC /AA17-24  
Location #: 419444




Photo #1

Bashor PC AA17-24 (123-32256) Wellsite

Temporarily Abandoned | TA

*Comment: Emergency number peeling.  
Consider replacing.*



Photo #2

Bashor PC AA17-24 Wellsite

Temporarily Abandoned | TA

*macro view*



## Inspection Photos

Location Name: BASHOR PC /AA17-24

Location #: 419444



**Photo #3**

**Bashor PC AA17-24** Wellsite

**Temporarily Abandoned | TA**

*Wellsite(s) entrance*



**Photo #4**

**Bashor PC AA17-24,17-15,17-16,17-23,  
Bashor 17-41** Battery site

**Abandoned: ALL Equipment Removed;**

*Formerly served:*

*Bashor 17-13,17-42, Bashor PC AA17-21,17-22,*

*Peppler PC AA17-20;*

*Plugged & Abandoned | PA; 5-well(s)*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources