

Inspection Photos
Location Name: BASHOR PC /AA17-23
Location #: 306260



Photo #1

Bashor PC AA17-23 (123-24320) Wellsite
Temporarily Abandoned | TA
CA: Undesirable weeds



Photo #2

Bashor PC AA17-23 Wellsite
Temporarily Abandoned | TA
macro view
CA: Undesirable weeds



Inspection Photos

Location Name: BASHOR PC /AA17-23

Location #: 306260



Photo #3

Bashor PC AA17-23 Wellsite

Temporarily Abandoned | TA

Wellsite(s) entrance



Photo #4

**Bashor PC AA17-24,17-15,17-16,17-23,
Bashor 17-41** Battery site

Abandoned: ALL Equipment Removed;

Formerly served:

Bashor 17-13,17-42, Bashor PC AA17-21,17-22,

Peppler PC AA17-20;

Plugged & Abandoned | PA; 5-well(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources