

INSPECTION PHOTOS

Well: APACHE CANYON 19-06


API #: 05-071-08824

INSPECTION DOC #: 716302138

Operator: OGRIS OPERATING LLC 10758

Inspection date: 4/7/2026

County: Las Animas


OGRIS
OPERATING, LLC

~~(719) 719-497-0446~~

WDID 1912482 or 911
PERMIT 74225

APACHE CANYON 19-06
SE/NW 19-34S-67W
NAD83
Lat. 37.072711
Long. 104.932834

API# 05-071-08824

Network: Apr 7, 2026 at 1:23:43 PM MDT
Local: Apr 7, 2026 at 1:23:43 PM MDT
+37.072973, -104.932837

PHOTO 2: WELL SIGN



Network: Apr 7, 2026 at 1:22:32 PM MDT
Local: Apr 7, 2026 at 1:22:32 PM MDT
+37.073005, -104.933284

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT. Vacuum pump observed on well without ECMC approval. **Provide ECMC with documentation showing approval of use of vacuum pump PER RULE 432. CA DATE 4/23/2026.**



PHOTO 5: UNUSED EQUIPMENT (1-3" RISER AND 1-2" RISER NOT IN USE OR MARKED). REMOVE RISERS IF THEY NOT IN USE OR USEFUL OR MARK RISER W/ A PERMANENT SIGN OR STICKER SHOWING WHAT IT IS USED FOR PER RULE 606. CA DATE 4/23/2026.