

INSPECTION PHOTOS

Well: APACHE CANYON 19-02V

API #: 05-071-07410

INSPECTION DOC #: 716302140

Operator: OGRIS OPERATING LLC 10758

Inspection date: 4/7/2026

County: Las Animas



PHOTO 2: WELL SIGN



Network: Apr 7, 2026 at 1:51:58 PM MDT
Local: Apr 7, 2026 at 1:51:58 PM MDT
+37.075713, -104.926957
279° W

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT. Vacuum pump observed on well without ECMC approval. **Provide ECMC with documentation showing approval of use of vacuum pump PER RULE 432. CA DATE 4/23/2026.**