

# INSPECTION PHOTOS

**Well: APACHE CANYON 18-16**

**API #: 05-071-08928**

**INSPECTION DOC #: 716302142**

**Operator: OGRIS OPERATING LLC 10758**

**Inspection date: 4/7/2026**

**County: Las Animas**



**OGRIS**  
OPERATING, LLC

**719-497-0446**

WDID 912678  
PERMIT 74041

or 911

**Apache Canyon 18-16**  
**SE/SE 18-34S-67W**  
**NAD 83**

**Lat. 37.077042**

**Long. 104.921064**

**API# 05-071-08928**

Network: Apr 7, 2026 at 2:14:53 PM MDT

Local: Apr 7, 2026 at 2:14:53 PM MDT

37.077042 -104.921064

PHOTO 2: WELL SIGN



Network: Apr 7, 2026 at 2:13:54 PM MDT  
Local: Apr 7, 2026 at 2:13:54 PM MDT  
+37.076917, -104.921546  
316° NW

PHOTO 3: LOCATION.



- Network: Apr 7, 2026 at 2:14:14 PM MDT  
Local: Apr 7, 2026 at 2:14:14 PM MDT  
+37.076988,-104.921164

PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: GAUGE HATCH IS STILL OPEN. THIS HATCH MUST BE KEPT CLOSED WHEN NOT GAUGING TANK.

Network: Apr 7, 2026 at 2:14:45 P  
Local: Apr 7, 2026 at 2:14:45 P  
+37.077167, -104.

Las Animas  
Remark: Energy and Carbon Management Com.