

Inspection Photos

April 6th, 2026

Operator: Williford Resources

Location ID: 325677

Inspection Document #: 714003548

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Angelina 8

April 6, 2026
9° N



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Angelina 8



Photo 2. View of unused risers that remain on the western edge of the pad.