

Final Reclamation and Stormwater Inspection

April 1, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 310593

Well Name: ENTERPRISE- USX XX #21-6

Inspection Document #: 718601554

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ENTERPRISE- USX XX #21-6

Location ID: 310593



Photo 1. Looking North down the former access road from the tank battery location. The first approximately 500 ft of access road has little desirable vegetation establishment and consists primarily of undesirable weeds such as kochia and russian thistle.



Photo 2. Looking down the northern part of the access road towards the well location. This picture was taken near a fence junction to the west. Desirable perennial vegetation has established on this portion of the former access road.



Inspection Photos

Location Name: ENTERPRISE- USX XX #21-6

Location ID: 310593



Photo 3. Looking east across the location. No oil and gas equipment remains on the location. Desirable perennial species such as crested wheatgrass and western wheatgrass were observed throughout the location and appear to be progressing towards 80% coverage of the reference area.



Photo 4. Looking north from wellbore. See photo 3 comments.



Inspection Photos

Location Name: ENTERPRISE- USX XX #21-6

Location ID: 310593



Photo 5. Looking east from wellbore. See photo 3 comments.



Photo 6. Looking south from wellbore. See photo 3 comments.



Inspection Photos

Location Name: ENTERPRISE- USX XX #21-6

Location ID: 310593



Photo 7. Looking west from wellbore. See photo 3 comments.



Photo 8. Reference vegetation to the east of well location. Vegetation consists primarily of crested wheatgrass and western wheatgrass. List C noxious weed cheatgrass is also present in the reference area.

