

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC CARNEY C T #8-34 PAD

Location ID: 314250

Date: 03/24/2026



Photo # 3767 Entrance to location



Photo # 3769 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC CARNEY C T #8-34 PAD

Location ID: 314250

Date: 03/24/2026



Photo # 3770 Location

Photo # 3780 NE corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC CARNEY C T #8-34 PAD

Location ID: 314250

Date: 03/24/2026



Photo # 3781 SE corner of location



Photo # 3782 SW corner of location

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC CARNEY C T #8-34 PAD

Location ID: 314250

Date: 03/24/2026



Photo # 3783 NW corner of location

Photo # 3788 Debris

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC CARNEY C T #8-34 PAD

Location ID: 314250

Date: 03/24/2026



Photo # 3789 Debris



Photo # 3790 Debris