

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH UNIT-66S100W/1NWSE

Location ID: 323847

Date: 3/31/2026



Mar 31, 2026 at 12:16:58
+39.562504,-108.499203
De Beque CO 81630
United States



Mar 31, 2026 at 12:19:31
+39.562327,-108.499133
De Beque CO 81630
United States

Location Overview – Photo #03356


Location – Photo #03359

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH UNIT-66S100W/1NWSE

Location ID: 323847

Date: 3/31/2026



Location – Photo #03358



Location – Photo #03357

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH UNIT-66S100W/1NWSE

Location ID: 323847

Date: 3/31/2026



No Erosion Controls Installed at Stream Crossing – Photo #03365



No Erosion Controls Installed at Stream Crossing – Photo #03366