

Inspection Photos

API: 071-07940

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/7/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Well sign posted at meter shed.



Inspection Photos



Photo 2. There was a dripping leak at the wellhead.



Inspection Photos



Photo 3. There was wet soils and a dripping leak at the tank which was inside secondary containment.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07940 | Date: 4/7/2026