

# Inspection Photos

API: 071-06435

Operator: OGRIS OPERATING LLC

Inspection Date: 4/7/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at reclamation area at the west side of canyon.



## Inspection Photos



**Photo 2.** Facing south toward the canyon bottom. There are noxious weeds at red arrow from last years growth.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06435 | Date: 4/7/2026

## Inspection Photos



**Photo 3.** View of noxious weeds (Plumeless thistle) from last years growth. There were already rosettes beginning to emerge.



## Inspection Photos



**Photo 4.** Facing south along the reclamation in the canyon bottom. There are noxious weeds at red arrow from last years growth.



## Inspection Photos



**Photo 5.** Facing northeast at the drainage crossing.



## Inspection Photos



**Photo 6.** Facing northeast at reclamation area at the east side of canyon. There are noxious weeds at red arrow from last years growth.



## Inspection Photos



**Photo 7.** Facing northeast at reclamation area at the east side of canyon.

