

Inspection Photos

API: 071-06409

Operator: OGRIS OPERATING LLC

Inspection Date: 4/7/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the location. The perennial vegetation is progressing..



Inspection Photos



Photo 2. East side of the location facing west.



Inspection Photos



Photo 3. Facing toward the west side of the location. This area has more bare soils that need additional reseeding.



Inspection Photos



Photo 4. Facing southeast at the location. This area has more bare soils that need additional reseeding. This area could be hand seeded and raked.

