

Inspection Photos  
Location Name: Community 1  
Location ID: 319888



Photo 1 Location access.

Photo 2 Location.

Inspection Photos  
Location Name: Community 1  
Location ID: 319888



Photo 3 Tank Battery.

Photo 4 Tank battery sign.

Inspection Photos  
Location Name: Community 1  
Location ID: 319888



Photo 5 Tank Battery.

Photo 6 ECD.

Inspection Photos  
Location Name: Community 1  
Location ID: 319888




Photo 7 Wellsite.

Photo 8 Wellsite sign.

Inspection Photos  
Location Name: Community 1  
Location ID: 319888



Photo 9 Trash & debris outside of the wellsite fence.

Photo 10 Wellsite.

Inspection Photos  
Location Name: Community 1  
Location ID: 319888



Photo 11 Stained soil by the wellhead.

Photo 12 Wellhead.

Inspection Photos  
Location Name: Community 1  
Location ID: 319888



Photo 13 Trash & debris inside wellsite fencing.

Photo 14 Trash & debris inside wellsite fencing.