

# Inspection Photos

Location Name: AURORA USX AB/25-11P

Location #: 413776



**Photo #1**

**Aurora USX AB 25-11P (123-30351) Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement-surface**



**Photo #2**

**Aurora USX AB 25-11P Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement-surface**

*Site safety signage*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: AURORA USX AB/25-11P**  
**Location #: 413776**

**Photo #3**

**Aurora USX AB 25-11P Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Cement-surface**  
*JSA; 2026-04-07*



**Photo #4**

**Aurora USX AB 25-11P Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Cement-surface**  
*Well; cmt ≈ 6' below.*



## Inspection Photos

Location Name: AURORA USX AB/25-11P

Location #: 413776



**Photo #5**

**Aurora USX AB 25-11P Wellsite**

**Plugging & Abandoned | PA**

**Plugging Ops; Cementing: Cement-surface**

*Wellsite entrance*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources