

Inspection Photos

April 8th, 2026

Operator: Enduring Resources

Location ID: 325158

Inspection Document #: 714003556

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 11

April 8, 2026
156° SE



Photo 1. View of well pad taken from the northern edge facing center.

April 8, 2026
324° NW



Photo 2. View of deep rutting occurring on the active pad.

April 8, 2026
163° S



Photo 3. Deep rutting along the access road.

