

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNE

Location #: 302509



Photo #1

Bashor State AA 16-02 (123-29254) Wellsite

Temporarily Abandoned | TA

CA: Undesirable weeds

Affix sign to well or fencing.

prior photo



Photo #2

Bashor State AA 16-02 Wellsite

Temporarily Abandoned | TA

CA: Mitigated.

Undesirable weeds; CLEARED

Operator photo: 2026-04-06



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNE

Location #: 302509



Photo #3

Bashor State AA 16-02 Wellsite

Temporarily Abandoned | TA

macro view

CA: Undesirable weeds

prior photo



Photo #4

Bashor State AA 16-02 Wellsite

Temporarily Abandoned | TA

macro view

CA: Mitigated.

Undesirable weeds; CLEARED

Operator photo: 2026-04-06



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNE

Location #: 302509



Photo #5

Bashor State AA 16-02 Wellsite

Temporarily Abandoned | TA

Wellsite(s) entrance

prior photo



Photo #6

Bashor State AA 16-08, 16-01, 16-02, 16-07,

Bashor State 16-18 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Bashor State AA 16-09, 16-17, Bashor State 16-22;

Plugged & Abandoned | PA; 3-well(s); prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources