

Final Reclamation Inspection

March 30, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 319628

Inspection Document #: 718801537

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BEEBE DRAW #1
Location ID: 319628



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*) were observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BEEBE DRAW #1
Location ID: 319628



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BEEBE DRAW #1
Location ID: 319628



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the well location, facing east. Photo illustrates that reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed.

Inspection Photos
Location Name: BEEBE DRAW #1
Location ID: 319628



Photo 7. Photo taken of the access road to the well location, facing west, away from the location. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities have taken place and perennial grass is establishing. However, vegetation establishment does not meet Rule 1004 standards.



Inspection Photos
Location Name: BEEBE DRAW #1
Location ID: 319628



Photo 9. Photo taken of the tank battery location, facing south. See comments under Photo 8.



Photo 10. Photo taken of the tank battery location, facing west. See comments under Photo 8.

Inspection Photos
Location Name: BEEBE DRAW #1
Location ID: 319628



Photo 11. Photo taken of ground cover at the tank battery location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 12. Photo taken of the reference area to the location, south of the well location, facing south. Photo illustrates perennial grass and weedy annual vegetation.