

Final Reclamation Inspection

March 30, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 310749

Inspection Document #: 718801546

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FLIPPIN #25BU
Location ID: 310749



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: FLIPPIN #25BU
Location ID: 310749



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: FLIPPIN #25BU
Location ID: 310749



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground and perennial grass.



Photo 6. Photo taken of the access road to the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place along the road, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including russian thistle (*Salsola tragus*) was observed

Inspection Photos
Location Name: FLIPPIN #25BU
Location ID: 310749



Photo 7. Photo taken of the reference area to the location, southeast of the well location, facing east. Photo illustrates perennial grass and sand sagebrush.