

Final Reclamation Inspection

March 30, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 332373

Inspection Document #: 718801552

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OTIS STATE G #36-19
Location ID: 332373



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place and perennial vegetation is establishing at the location. However, vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: OTIS STATE G #36-19
Location ID: 332373



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: OTIS STATE G #36-19
Location ID: 332373



Photo 5. Photo taken of the well location, facing northeast. See comments under Photo 1.



Photo 6. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and evidence of drill rows from seeding.

Inspection Photos
Location Name: OTIS STATE G #36-19
Location ID: 332373



Photo 7. Photo taken of the access road to the well location, facing west. Photo illustrates that final reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the reference area to the location, facing northeast. Photo illustrates perennial grass vegetation.