

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 4/9/2026



Location Overview – Photo #03495



Location/Weeds – Photo #03496

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 4/9/2026



Location/Weeds – Photo #03501



Location/Weeds – Photo #03506

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 4/9/2026



Stored Supplies – Photo #03505



Unmarked Deadman – Photo #03509

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 4/9/2026



Missing Tank Cover/Wildlife Entry Hazard – Photo #03507




Wellhead Pressure Gauge – Photo #03499

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 4/9/2026



Wellhead Pressure Gauge – Photo #03500



Downstream Pressure Gauge on Separator – Photo #03502

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 4/9/2026



**No BMPs Installed at Water Drainage/Stream Crossing –
Photo #03510**