

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC MCLAUGHLIN, A C #42

Location ID: 314477

Date: 04/9/2026



Photo # 4386 Entrance to location



Photo # 4392 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC MCLAUGHLIN, A C #42

Location ID: 314477

Date: 04/9/2026



Photo # 4393 Wellhead sign lacks public road used to access the well

Photo # 4399 Location

Inspection/Audit Photos


Location: SCOUT ENERGY MANAGEMENT LLC MCLAUGHLIN, A C #42

Location ID: 314477

Date: 04/9/2026



Apr 9, 2026 at 9:55:42 AM
 +40.141518, -108.902597
 134° SE
 81648
 Rio Blanco County
 ECMC



Apr 9, 2026 at 10:00:34 AM
 +40.141228, -108.902272
 73° E
 81648
 Rio Blanco County
 ECMC

Photo # 4402 Location

Photo # 4415 FORM 21