

# Inspection Photos

03/25/2026

Operator: GRMR Oil and Gas LLC #10524

Location ID: 312930

Inspection Doc: 719201007

Moffat County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 312930



**Photo 1:** Photos showing an overview of the location looking north and south, respectively. Desirable, perennial and uniform vegetation is present.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 312930



**Photo 2:** Photos showing an overview of the location looking east and west, respectively. Desirable, perennial and uniform vegetation is present.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 312930



**Photo 3:** Photos showing the southern access road leading to the location has been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 312930



**Photo 4:** Photo showing a small patch of Canada thistle, a List B noxious weed, is present at the northwestern end of the location. Weed management is required before the location receives a passing final reclamation inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GRMR Oil and Gass LLC #10524

Location ID: 312930



**Photo 5:** Photos showing the nearby eastern reference area is characterized as a big sagebrush shrubland.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources