

Inspection Photos

API: 009-06628

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 4/9/2026

County: BACA



Inspection Photos



Photo 1. Facing east at the beginning of the reclaimed access road.



Inspection Photos



Photo 2. Drone aerial photo along the former access road. The road has been recontoured and reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06628 | Date: 4/9/2026

Inspection Photos



Photo 3. Drone aerial photo facing east toward the location.



Inspection Photos



Photo 4. Drone aerial photo facing east toward the location. The location has been recontoured and reclaimed.



Inspection Photos




Photo 5. Drone aerial photo facing southwest toward the location.



Inspection Photos



Photo 6. Drone aerial photo facing southwest at the location. It appears perennial vegetation is establishing.

