

Remediation Status Sheet

Inspection Date: 4/13/2026

Location Information

Operator:	KPK	Location Name:	Dechant State 3 Flowline
Spill ID:	487984	County:	Weld
Remediation Project No:	39579	City/Township:	None

Reporting Status

Spill Date:	09/20/2024	Last Form 27 Submitted:	03/14/2025
Spill Open?	No	Last Form 27 Doc No:	404116584
Spill Closure Due:	NA	Next Form 27 Due:	6/12/2025

Sensitive Receptors

High Priority Habitat:	No	Notes:
Wetlands:	No	Notes:
Surface Water:	> 500'	Notes:
Residence:	> 500'	Notes:
Water Well:	> 500'	Notes:

Remediation Status*

Soil samples collected and submitted:	No	Notes:
Soil Impacts remaining in-situ:	Yes	Notes:
<i>Organics:</i>	Yes	Notes: Hydrocarbon stained soil and free product visible in situ
<i>Soil Suitability:</i>	Unknown	Notes:
<i>Metals:</i>	Unknown	Notes:
Soil POC achieved:	Unknown	Notes:
Impacts to groundwater**:	Unknown	Notes:
Monitoring Wells Installed:	No	Notes:
Groundwater POC achieved:	Unknown	Notes:

*Remediation Status based off most current information per Form 19/27 submittal

**Impacts to groundwater include sheen/free product observed on groundwater, impacted soil in contact with groundwater, or analytical

POC = Point of Compliance