

Final Reclamation Inspection

March 23, 2026

Operator: PDC ENERGY INC

Location ID: 472842

Inspection Document #: 720300204

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Skurich-Rothe/33-6
Location ID: 472842



Photo 3: Photo taken from the location facing north. Most of the disturbance area is bare soil. Vegetation present is undesirable.



Photo 4. Photo taken from the location facing east. See comment under photo 3.

Inspection Photos
Location Name: Skurich-Rothe/33-6
Location ID: 472842



Photo 5. Photo taken from location facing south. See comment under photo 3.



Photo 6. Photo taken from the location facing west. See comment under photo 3.

Inspection Photos
Location Name: Skurich-Rothe/33-6
Location ID: 472842



Photo 7. Photo taken from location west . See comment under photo 3.



Photo 8. Photo taken from wester corner of disturbance area facing east showing disturbance area is mostly bare soil.

