

Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



Photo #1

Owl Creek 13 (123-11934) Wellsite

Temporarily Abandoned | TA

CA: Signage w/ Emergency #, NOT posted



Photo #2

Owl Creek 13 Wellsite

Temporarily Abandoned | TA

Macro view



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



Photo #3

Owl Creek 13 Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 322722



Photo #4

Owl Creek 13 Battery site

Inactive | Shut-down

Well(s)ite(s), Battery site entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources