

## Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



**Photo #1**

Owl Creek 13 Battery site

**Inactive | Shut-down**

*Equipment Documented; Loc ID: 322722*



**Photo #2**

Owl Creek 13 Battery site

**Inactive | Shut-down**

*Well(s) site, Battery site entrance*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



**Photo #3**

Owl Creek 13 Battery site

**Inactive | Shut-down**

*Crude oil tank(s), produced H2O vault(s): SE corner*



**Photo #4**

Owl Creek 13 Battery site

**Inactive | Shut-down**

*ECD(s), Separator(s)*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

# Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



**Photo #5**

**Owl Creek 13 Battery site**

**Inactive | Shut-down**

*Battery sign*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722

Associated Well(s)	API	Status
1. Owl Creek 13	123-11934	TA

### Photo #6

Owl Creek 13 Battery site

Inactive | Shut-down

Associated Well(s):

1: Temporarily Abandoned | TA



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources