

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Google Earth aerial of the location with the corresponding pit numbers

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 1 – Placard

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 2– Overview of location viewing from Southwest looking Northeast with Pit 1 on the right.

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 3– Culvert is diverting fluid from the fenced-in pit area north to the access road of the pit facility. Discharge point for facilities surface discharge permit is unknown. Viewing from the Northside of location looking South.

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 4 - Pit 1 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 5 - Pit 1 looking west. Disturbance along the pit walls. Note that most of the liner has been removed with some liner remaining in the base of the pit.

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 6 - Pit 1 looking east. Disturbance along the pit walls. Note that the majority of the liner has been removed with some liner remaining in the base of the pit.

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 7 - Pit 2 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 8 - Pit 2 looking west. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 9 - Wildlife mortality
in pit 2**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 10 - Pit 2 looking east. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 11 - Pit 3 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 12 - Pit 3 looking west. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 13 - Pit 3 looking east. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 14 - Pit 4 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 15 - Pit 4 looking
southeast**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 16 - Pit 4 looking west. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 17 - Pit 5 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 18 - Pit 5 looking west. Liner is in disrepair.
Depth of fluids is approximately 12" to 24".**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 19 - Pit 5 looking east. Liner is in disrepair.
Depth of fluids is approximately 12" to 24".**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 20- Pit 6 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 21 - Pit 6 looking West. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 22 - Pit 6 looking East.. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 23 - Pit 7 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 24 - Pit 7 looking West. Liner is in disrepair. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 25 - Pit 7 looking East. Liner is in disrepair.
Depth of fluids is approximately 12" to 24".**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 26 - Pit 8 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 27 - Pit 8 looking West. Liner is in disrepair. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 28 - Pit 8 looking East. Liner is in disrepair.
Depth of fluids is approximately 12" to 24".**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 29 - Pit 9 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 30 - Pit 9 looking West. Liner is in disrepair.
Depth of fluids is approximately 12" to 24".**

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 31 Pit 9 looking East

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 32 - Pit 10 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 33 - Pit 10 valve can

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



Photo 34 - Pit 10 looking West. Depth of fluids is approximately 12" to 24".

Inspection Photos
Location: Breeze 11-20 Pit
Location ID: 316771, Pit ID 262410



**Photo 35 - Pit 10 looking East. NOTE: Liner is in disrepair.
Depth of fluids is approximately 12" to 24".**