

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404596350
Receive Date:
04/10/2026

Report taken by:
Alexander Ahmadian

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers Phone: <u>(970) 304-5000</u> Mobile: <u>()</u>
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Dan Peterson</u>	Email: <u>RBUEUF27@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 41643 Initial Form 27 Document #: 404273289

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>001-07202</u>	County Name: <u>ADAMS</u>
Facility Name: <u>CHAMPLIN 67 AMOCO F UNIT 1</u>	Latitude: <u>39.865788</u>	Longitude: <u>-104.448071</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWNW</u>	Sec: <u>21</u>	Twp: <u>2S</u>	Range: <u>63W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Grassland
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Riverine 0.23mi E

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- X E&P Waste
Other E&P Waste
Non-E&P Waste
Produced Water
Workover Fluids
Oil
Tank Bottoms
Condensate
Pigging Waste
Drilling Fluids
Rig Wash
Drill Cuttings
Spent Filters
Pit Bottoms
Other (as described by EPA)

DESCRIPTION OF IMPACT

Table with 4 columns: Impacted?, Impacted Media, Extent of Impact, How Determined. Rows include UNDETERMINED GROUNDWATER and SOILS.

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the CHAMPLIN 67 AMOCO F UNIT 1 wellhead cut and cap. The wellhead was cut and capped per ECMC rules on October 17, 2025.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

X Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation.

Proposed Groundwater Sampling

X Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation a grab groundwater sample will be collected and analyzed for all organic compounds and inorganic parameters per ECMC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the wellhead area occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 1

Number of soil samples exceeding 915-1 1

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 100

NA / ND

-- Highest concentration of TPH (mg/kg) 174

-- Highest concentration of SAR 8.74

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) _____

Number of groundwater monitoring wells installed _____

Number of groundwater samples exceeding 915-1 _____

_____ Highest concentration of Benzene (µg/l) _____

_____ Highest concentration of Toluene (µg/l) _____

_____ Highest concentration of Ethylbenzene (µg/l) _____

_____ Highest concentration of Xylene (µg/l) _____

_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

_____ Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Three background soil samples were collected on 10/20/2025 from an area not impacted by oil and gas development and at depths and lithologies (silty sands and clayey sands – SM, SC) comparable to those of the confirmation soil samples collected at the location. The samples were analyzed by a certified laboratory for Table 915-1 metals and SSR parameters using ECMC approved Methods. Based on the background analytical results summarized below, the following Table 915-1 metals were within the maximum observed background values (listed in mg/kg):
Arsenic Max*1.25 = 6.9
Barium Max*1.25 = 346
Additional background samples will be collected to determine site specific background concentrations of SAR.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

Is further site investigation required?

A supplemental site investigation (SSI) will be completed to collect additional background samples to determine if elevated levels of SAR are attributed to native soil conditions at the site. The proposed background sample locations are included in the Site Map attached to Form 27 document number 404481400. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation (SSI) will be completed to collect additional background samples to determine if elevated levels of SAR are attributed to native soil conditions at the site. The proposed background sample locations are included in the Site Map attached to Form 27 document number 404481400. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during site investigation or excavation activities. If groundwater is encountered at the site, groundwater sampling will be conducted in accordance with the Proposed Groundwater Sampling section in this Form 27.

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeded program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 10/17/2025

Proposed date of completion of Reclamation. 10/31/2027

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/10/2025

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 10/17/2025

Proposed site investigation commencement. 07/16/2026

Proposed completion of site investigation. 07/16/2026

REMEDIAL ACTION DATES

Proposed start date of Remediation. 07/10/2026

Proposed date of completion of Remediation. 01/10/2027

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the decommissioning of the CHAMPLIN 67 AMOCO F UNIT 1 wellhead and necessity for supplemental site investigation activities adjacent to the wellhead.

OPERATOR COMMENT

This Form 27 is being submitted to include a 2Q 2026 timeline update for the CHAMPLIN 67 AMOCO F UNIT 1 wellhead (REM #41643). A supplemental site investigation (SSI) will be completed to collect additional background samples to determine if elevated levels of SAR are attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

Three background soil samples were collected on 10/20/2025 from an area not impacted by oil and gas development and at depths and lithologies (silty sands and clayey sands – SM, SC) comparable to those of the confirmation soil samples collected at the location. The samples were analyzed by a certified laboratory for Table 915-1 metals and SSR parameters using ECMC approved Methods. Based on the background analytical results summarized below, the following Table 915-1 metals were within the maximum observed background values (listed in mg/kg):

Arsenic Max*1.25 = 6.9

Barium Max*1.25 = 346

Additional background samples will be collected to determine site specific background concentrations of SAR.

This project is waiting for required background samples to be collected and analyzed. We anticipate that background samples at the site will occur on July 16, 2025. Access has been requested and is awaiting review.

Pursuant to Rule 913.e, quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Tahni Jungst, P.E.

Title: Environmental Consultant

Submit Date: 04/10/2026

Email: CVX-PM@cdhconsult.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Alexander Ahmadian

Date: 04/16/2026

Remediation Project Number: 41643

COA Type

Description

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

<u>Att Doc Num</u>	<u>Name</u>
404596350	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	ECMC has processed this form as an update without technical review; no data was attached thus approval of this form does not imply any agreement with comments on completion of site investigation or alteration of site plan. All ongoing/unaddressed comments/COAs from previous Forms remain applicable. Operator shall not delay execution of remedial or investigative actions while waiting for ECMC approval and may request expedited review if necessary.	04/16/2026

Total: 1 comment(s)