

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404621848

Date Received:

04/17/2026

**SPILL/RELEASE REPORT (SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

Spill report taken by:

Rollins, Grace

Spill/Release Point ID:

493741

**OPERATOR INFORMATION**

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 515-1727</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>( )</u>
Contact Person: <u>Eve Bugarin</u>		Email: <u>DJRemediation Forms @oxy.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

**INITIAL SPILL/RELEASE REPORT**

Initial Spill/Release Report Doc# 404611185

Initial Report Date: 04/07/2026 Date of Discovery: 04/07/2026 Spill Type: Recent Spill

**Spill/Release Point Location:**

QTRQTR NWSW SEC 24 TWP 3N RNG 68W MERIDIAN 6

Latitude: 40.210961 Longitude: -104.959578

Municipality (if within municipal boundaries): Mead County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

**Reference Location:**

Facility Type: TANK BATTERY

Facility/Location ID No 488257

Spill/Release Point Name: BENSON FARMS 11N 32C 12N-23HZ O SA

Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Partly Cloudy 55°F

Surface Owner: FEE

Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A release of approximately 2.5 bbls of oil was identified at the Benson Farms 11N 32C 12N-23HZ O SA production facility due to equipment failure at a Lease Automatic Custody Transfer (LACT) unit. This release became reportable following the removal of more than 10 cubic yards of potentially impacted soil. This release has been controlled and is no longer active. Assessment activities are ongoing. The assessment details will be summarized in a forthcoming Form 19 supplemental report. The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. A photo log is attached.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
4/7/2026	Colorado Parks & Wildlife	Colorado Parks & Wildlife	-	Notified via email
4/7/2026	Municipality of Mead	Municipality of Mead	-	Notified via email
4/7/2026	Surface Owner	Surface Owner	-	Notified via phone
4/7/2026	Weld County	Weld County	-	Notified via email

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

Yes Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: Threatened to Impact Public Water System: n/a  
 Residence or Occupied Structure: n/a Livestock: n/a  
 Wildlife: n/a Publicly-Maintained Road: n/a

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
 Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
 Was there damage during excavation? \_\_\_\_\_  
 Was CO 811 notified prior to excavation? \_\_\_\_\_

Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): 10

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

Yes Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

No Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location  Off-Location Flowline right of way

No Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

No Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 04/17/2026

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>2</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER	<u>0</u>	<u>0</u>	<input type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply)  Soil  Groundwater  Surface Water  Dry Drainage Feature

Surface Area Impacted: \_\_\_\_\_ Length of Impact (feet): \_\_\_\_\_ Width of Impact (feet): \_\_\_\_\_

Depth of Impact (feet BGS): \_\_\_\_\_ Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

Assessment and remediation activities are being conducted under Table 915-1 standards and the impacted soil will be removed. The analytical results and assessment details will be provided in a supplemental report. A photo log is included as an attachment.

Soil/Geology Description:

Clayey sand (SC)

Depth to Groundwater (feet BGS) 20 Number Water Wells within 1/2 mile radius: 4

If less than 1 mile, distance in feet to nearest

Water Well	<u>1140</u>	None <input type="checkbox"/>	Surface Water	<u>240</u>	None <input type="checkbox"/>
Wetlands	<u>260</u>	None <input type="checkbox"/>	Springs	_____	None <input checked="" type="checkbox"/>
Livestock	<u>870</u>	None <input type="checkbox"/>	Occupied Building	<u>890</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 04/17/2026

Root Cause of Spill/Release Equipment Failure

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

LACT unit

Describe Incident & Root Cause (include specific equipment and point of failure)

A release of approximately 2.5 bbls of oil was identified at the Benson Farms 11N 32C 12N-23HZ O SA production facility due to equipment failure at a LACT unit. This release became reportable following the removal of more than 10 cubic yards of potentially impacted soil. This release has been controlled and is no longer active. Assessment activities are ongoing.

Describe measures taken to prevent the problem(s) from reoccurring:

Preventative measures are currently being assessed and will be addressed in the 90 day supplemental.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
    - Horizontal and Vertical extents of impacts have been delineated.
    - Documentation of compliance with Table 915-1 is attached.
    - All E&P Waste has been properly treated or disposed.
  - Work proceeding under an approved Form 27 (Rule 912.c).  
Form 27 Remediation Project No: \_\_\_\_\_
  - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Eve Bugarin

Title: Eng. Staff Environmental Date: 04/17/2026 Email: DJRemediation\_Forms@oxy.com

**COA Type****Description**

0 COA	

**ATTACHMENT LIST****Att Doc Num****Name**

404621861	TOPOGRAPHIC MAP
404621862	CORRESPONDENCE
404621863	PHOTO DOCUMENTATION

Total Attach: 3 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)