

Inspection Photos

04/09/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 323954

Inspection Doc: 719201043

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323954



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323954



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323954



Photo 3: Photos showing an overview of the southern and eastern interim areas, respectively. Interim areas were passed in previous inspection #692402381. Passing interim status is subject to change if conditions deteriorate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323954



Photo 4: Photos showing rilling and erosion behind separator equipment on the western portion of the location; maintenance is required. Comply With Rule 1002.f.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323954



Photo 5: Photos showing sediment appears to be discharging into neighboring pasture.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources